



A&A Leg Tutorial

Rev - Sept 23 2009
Part 6B added
No 6 and 6A reversed



It was found that sometimes the thickness of the parts (ie 5A, 6, 6A etc) were not exactly 0.250". This meant the overall thickness was not correct. Part 6B is included to get the proper thickness if needed.

Lay out the parts as follows for assembly and to make sure you have all the parts