



Lay out the parts as shown. The parts below will be sandwiched together in the order they are shown. Look at the next page for the assembly order for the box section.

The ankle was constructed this way mainly for the A&A frame. It is also designed to allow for the full travel in the frame for 2-3-2 modes.

The above parts are the styrene skins for the ankle area to cover the lines produced when sandwiching of the parts

items No 50 are the 3 legged mode ankle wedges

